

**Sites at which response actions have been completed during previous year.**

Date response action completed	Site Name	Name of Owner	Location		Response Action	Institutional		Contaminate	Size (Acres)
			Street Address	Latitude / Longitude		Present	Type		
9/1/2012	Former Philadelphia Furniture Manufacturing Company	SNI	100-23 Rochester Street, Salamanca, NY	42.159602/ -78.711009	Phase 1 ESA	not applicable at this time		unknown	5